



**Intertek**

PROGRAM ADMINISTRATOR  
DEPARTMENT ALECP  
INTERTEK  
3933 U.S. ROUTE 11  
CORTLAND, NY 13045-0950

ADB SAFEGATE AMERICAS, LLC  
977 GAHANNA PKWY  
COLUMBUS, OH 43230

REVISION DATE: May 30, 2017

ORIGINAL ISSUE DATE: July 13, 2010

Recertification due: January 2018

An Activity Sponsored and Administered by  
Intertek

**AIRPORT LIGHTING  
EQUIPMENT  
CERTIFICATION PROGRAM**

**CERTIFICATE OF  
CONFORMANCE**

The product described below is hereby approved for listing in the next issue of the Federal Aviation Administration (FAA) Advisory Circular (AC) 150/5345-53, Appendix 3 Addendum "Airport Lighting Equipment Certification Program. The approval is based on successful completion of tests in accordance with the specifications listed in, and the requirements for approval described in the Advisory Circular, and the reporting to the Program Administrator the results of such tests, accompanied by related documents by an Intertek recognized testing laboratory. The certification is not valid for a product modified with non-OEM replacement parts or non-production components.

L-861 – Lights, Runway & Taxiway Edge, Medium Intensity (AC 150/5345-46E)		
Manufacturer	Type	Manufacturer's Catalog Number
ADB Safegate Americas, LLC	L-861(L)	IMIL-11X0 (418); IMIL-12X0 (418); IMIL-21X0 (418) IMIL-22X0 (418); IMIL-31X0 (418); IMIL-32X0 (418) IMIL-41X0 (418); IMIL-42X0 (418); IMIL-51X0 (418) IMIL-52X0 (418)
	L-861E(L)	IMIL-71X0 (421)(422); IMIL-72X0 (421)(422) IMIL-81X0 (421); IMIL-82X0 (421); IMIL-91X0 (422) IMIL-92X0 (422)
	L-861T (L)	IMIL-D1X0 (571); IMIL-D2X0 (571)
Equipment meets the requirements of FAA Engineering Brief No. 67D additional requirements for "Light Sources Other Than Incandescent and Xenon for Airport and Obstruction Lighting Fixtures" dated March 6, 2012.		

1. This Equipment requires continuing validation in accordance with the requirements of AC 150/5345-53, and the Intertek Airport Lighting Equipment Certification Program.
2. Product tested and Report issued by: Intertek; ADB Airfield Solutions

(A) Report No: 100113874CRT-001;  
100019704CRT-001; 100182420CRT-001  
100150304CRT-001; 100190999MIN-004;  
113A0615; 100999572CRT-002A; 113A0652;  
100405253MIN-030; 100405253CRT-001

(B) Date of Report: 6/2010; 6/2010; 8/2010; 8/2010;  
9/2010; 3/2013; 11/2013; 12/2013; 5/2012; 3/2012

NOTE: PLEASE REVIEW, AND ADVISE ADMINISTRATOR AT INTERTEK IMMEDIATELY IF DATA, AS SHOWN, NEED TO BE CORRECTED.

Approved for Certification by:

Jeremy N. Downs, P.E., Program Administrator  
Date: May 30, 2017