



PROGRAM ADMINISTRATOR
DEPARTMENT ALECP
INTERTEK
3933 U.S. ROUTE 11
CORTLAND, NY 13045-0950

ADB SAFEGATE AMERICAS, LLC
977 GAHANNA PKWY
COLUMBUS, OH 43230

REVISION DATE: May 30, 2017

ORIGINAL ISSUE DATE: September 11, 2014

Recertification due: January 2018

An Activity Sponsored and Administered by
Intertek

**AIRPORT LIGHTING
EQUIPMENT
CERTIFICATION PROGRAM**

**CERTIFICATE OF
CONFORMANCE**

The product described below is hereby approved for listing in the next issue of the Federal Aviation Administration (FAA) Advisory Circular (AC) 150/5345-53, Appendix 3 Addendum "Airport Lighting Equipment Certification Program. The approval is based on successful completion of tests in accordance with the specifications listed in, and the requirements for approval described in the Advisory Circular, and the reporting to the Program Administrator the results of such tests, accompanied by related documents by an Intertek recognized testing laboratory. The certification is not valid for a product modified with non-OEM replacement parts or non-production components.

| L-861 – Lights, Runway & Taxiway Edge, Medium Intensity (AC 150/5345-46E) | | |
|--|-----------|--|
| Manufacturer | Type | Manufacturer's Catalog Number |
| ADB Safegate Americas, LLC | L-861E(L) | IMIL-A1X0 (421)(422); IMIL-B1X0 (421); IMIL-C1X0 (422); IMIL-A2X0 (421)(422); IMIL-B2X0 (421); IMIL-C2X0 (422); |
| Equipment meets the requirements of FAA Engineering Brief No. 67D additional requirements for "Light Sources Other Than Incandescent and Xenon for Airport and Obstruction Lighting Fixtures" dated March 6, 2012. | | |

1. This Equipment requires continuing validation in accordance with the requirements of AC 150/5345-53, and the Intertek Airport Lighting Equipment Certification Program.

2. Product tested and Report issued by: Intertek

(A) Report No: 100113874CRT-001;
100019704CRT-001; 100150304CRT-001;
100190999MIN-004; 100405253CRT-001;
100405253CRT-002; 100999572CRT-002A;
113A0615

(B) Date of Report: 6/2010; 6/2010; 8/2010; 9/2010;
3/2012; 6/2012; 11/2013; 3/2013

NOTE: PLEASE REVIEW, AND ADVISE
ADMINISTRATOR AT INTERTEK IMMEDIATELY
IF DATA, AS SHOWN, NEED TO BE
CORRECTED.

Approved for Certification by:

Jeremy N. Downs, P.E., Program Administrator
Date: May 30, 2017