

## Product Discontinuation Notice

Dear Valued Customer,

This notice is to inform you that ADB Safegate will discontinue the manufacturing of the **FAA L-849 Runway End Identification Lights (REILs)** listed in the “Product Transition Table” below.

In accordance with ADB Safegate product discontinuation policy, we are hereby giving notice of these changes so that our customers can adjust their product part number purchasing records, or make any final lifetime purchases of discontinued product(s) to support their operations.

Product Transition Table	
<b>Product Name</b>	L-849 REIL Runway End Identification Lights (44A1161/xx)
<b>Reason(s) for Discontinuance</b>	We are partnering with Flash Technology to serve the market for Xenon REILs.
<b>Last time buy deadline</b>	<b>June 1, 2016</b>
	Last day to order complete products. Orders for discontinued products will not be accepted after this date.
<b>End-of-Support deadline</b>	<b>January 1, 2018</b>
	Spare parts will no longer be available for warranty or non-warranty support, and technical support will be limited to fee-based repair work.

Equivalent product replacements are available for this product as indicated in the “Product Replacement Table” below.

Product Replacement Table	
Discontinued Part Number	Replacement Part Number
44A1161/xx	<p>We have an agreement in place with Flash Technology (SPX) (<a href="#">Flash Technology web site</a>) to utilize their strobe technology in the FAA and Canadian markets. This includes ODAL (omni-directional) requirements.</p> <p>ICAO customers outside of the US are also able to utilize their technology if it meets their requirements.</p> <p>Flash Technology products are shown here on the ADB Safegate Product Center: <a href="#">Product Center Flash Technology Xenon REILs</a></p>

### Spare Parts:

The table below shows spare parts that were available for the ADB Safegate L-849 Xenon REILs. The list is based on common spare parts for the REILs, as shown in the manual or on the catalog sheet. While ADB Safegate will make every effort to maintain spare parts on the schedule shown, the availability of older technology components may affect that date. Xenon flash lamps, as well as parts common to other products will remain available.

### Phaseout Spare Parts - Xenon REIL

Part No	Description	Notes
44D1988/1100	Current Sensing Assembly - Single Step	
44D1988/2100	Current Sensing Assembly - Three Step	
44B1164	High Voltage Diode Assembly	
44B1164/1	High Voltage Diode Assembly with Leads	
44B1157	Master Oscillator PCB Assembly (Style E)	
44B1156	Master Oscillator PCB Assembly (Style A/C)	
94A0602	Relay, Intensity Switching, DPDT, 110 VAC (No Power Adapter)	
53A0261	Relay, Input Power Switching, DPDT, 110 VDC (With Power Adapter)	
44B1165	Resistor Mounting Block Assembly	
44B1780/4	Trigger Transformer Assembly	
44B1105	Trigger Interface PCB	
44A7196	Input Power Switching PCB	

### Last-time Buy Conditions:

- All purchase orders for last-time buys are non-cancellable and non-returnable.
- For orders for only spare parts, a \$150 order minimum is required.
- For orders which include complete REILs, a \$2,000 order minimum is required.

We regret the inconvenience and impact this notice may cause. ADB Safegate Sales Representatives stand ready to answer any questions you may have or assist you with any final orders.