

PROGRAM ADMINISTRATOR DEPARTMENT ALECP INTERTEK 3933 U.S. ROUTE 11 CORTLAND, NY 13045-0950 ORIGINAL ISSUE DATE: October 27, 2020

Recertification due: March 2028

An Activity Sponsored and Administered by Intertek

MILLERBERND MANUFACTURING COMPANY 622 6th Street South Winsted, MN 55395

AIRPORT LIGHTING EQUIPMENT CERTIFICATION PROGRAM

CERTIFICATE OF CONFORMANCE

The product described below is hereby approved for listing in the next issue of the Federal Aviation Administration (FAA) Advisory Circular (AC) 150/5345-53, Appendix 3 Addendum "Airport Lighting Equipment Certification Program. The approval is based on successful completion of tests in accordance with the specifications listed in, and the requirements for approval described in the Advisory Circular, and the reporting to the Program Administrator the results of such tests, accompanied by related documents by an Intertek recognized testing laboratory. This Certificate is only confirmable in conjunction with equipment being listed in AC 150/5345-53, Appendix 3, Addendum, as currently published by the FAA. The certification is not valid for a product modified with non-OEM replacements parts or non-production components.

L-868 – Light Base, Load Bearing (AC 150/5345-42J)						
				Manufacturer's Catalog Number		
Mfg	Туре	Size	Class	Extensions	Flange Rings	Spacer Rings
	L-868 L-868	A A	IA IA	88E(X)	88SY(X) 88FY(X)	88S(X) 88SMB(X)
Millerbernd Manufacturing Company	L-868 L-868	A B	IA IA	128E(X)	88F(X) 128SY(X)	128S(X)
	L-868 L-868	B B	IA IA		128FY(X) 128F(X)	128SMB(X)
	L-868 L-868 L-868	C C C	IA IA IA	158E(X)	158SY(X) 158FY(X) 158F(X)	158S(X) 158SMB(X)

1. This Equipment requires continuing validation in accordance with the requirements of AC 150/5345-53, and the Intertek Airport Lighting Equipment Certification Program.

2. Product tested and Report issued by: Intertek

(A) Report No: 104239937CRT-001

NOTE: PLEASE REVIEW, AND ADVISE

IF DATA, AS SHOWN, NEED TO BE

ADMINISTRATOR AT INTERTEK IMMEDIATELY

(B) Date of Report: 9/2020

Approved for Certification by:

Jeremy N. Downs, P.E., Program Administrator Date: October 27, 2020

Form AL-3 1/2006

CORRECTED.