




ADB SAFEGATE

PRODUCT DISCONTINUATION NOTICE

TLP




**ADB
SAFEGATE**

Product Discontinuation Notice

Dear Valued Customer,

*This notice is to inform you that ADB SAFEGATE will discontinue the sourcing and supplying of the **TLP – Taxiway Low Protrusion Inset Lights**.*

In accordance with ADB SAFEGATE product discontinuation policy, we are hereby giving notice of these changes so that our customers can adjust their product part number purchasing records or make any final lifetime purchases of discontinued products to support their operations.

In this notice you can find necessary details about the discontinuation target dates, successor products, updated spare parts policy and last time buy conditions.

Customers for whom the discontinued product remains a base fixture of choice for long-term operation of their airfield are encouraged to engage into the phase out process as of receipt of this notice by providing forecast which will enable ADB SAFEGATE to consolidate acquisition of the parts carrying high potential of becoming obsolete on the medium or long-term.

We regret the inconvenience and impact this notice may cause. ADB SAFEGATE Sales Representatives stand ready to answer any questions you may have or assist you with any final orders or alternative solutions.

Rikard LARSSON & Wojciech GRZEGORCZYK
Product Manager Portfolio Rationalization
Project Manager



Discontinuation Planning

Product Name	<i>TLP - Taxiway Low Protrusion Inset Light</i>
Reason(s) for Discontinuance	Reduced demand and components availability
Forecast Deadline	31 October 2022
	Customers are requested to provide demand forecast for fixtures and spare parts for the period of the phase out process outlined below.
Last time buy and End-of-Support Deadline	30 September 2023
	Orders for complete fixtures and spare parts will be accepted until this date. No orders will be accepted beyond this date unless prior special arrangement will be made between the Customer and ADB SAFEGATE i.e. based on the forecast provided before the <i>Forecast Deadline</i> , above.

Replacement Product

Discontinued Part Numbers	Replacement Part Number
TLP All order codes starting with 1LP*4 and all their special subversions i.e. 1LP*4.1 . NOTE: Articles ending with "3" e.g. 1LP*3 have been already discontinued earlier and replaced by 1LP*4 being discontinued now.	AXON LED inset lights

Spare Parts Availability

The table below shows availability as described in the *End-of-Support deadline* section above.

TLP

SP code	SP name	Availability
1411.20.400	Metric screw kit 8" (with anti-rotation pins)	To discontinue after SP support end date
1411.20.410	UNC screw kit for 8"	Already discontinued
1411.20.411	UNC screw kit 8"	Already discontinued
1411.20.420	Metric nut kit 8"	To discontinue after SP support end date
1411.20.430	Self-locking metric nut kit 8" (H100)	To discontinue after SP support end date
1411.20.435	Self - locking metric nut kit 8" (H80)	Already discontinued
1411.20.441	Metric screw kit 8" (Germany)	To remain available
1411.20.482	Metric screw kit (France) 12"	To remain available
1411.20.452	UNC screw kit 12"	To remain available
1411.20.492	Metric screw kit 12" (Germany)	To remain available
1411.20.500	Self-locking nut kit 12" (H100)	To discontinue after SP support end date
1411.20.505	Self-locking metric nut kit 12" (H80)	Already discontinued
1411.20.522	Metric screw kit 8" (w/o anti-rotation pins)	To remain available
1411.21.000	Terminal block assembly with fixing hardware and with film disc cut-out	To discontinue after SP support end date
1411.21.010	Terminal block assy. without cut-out	To remain available until F-range discontinuation
1411.21.200	F-RANGE KIT CUT OUT	To discontinue after SP support end date
1412.10.000	TLP V3: Inner pan assembly for one lamp	Already discontinued
1412.10.001	TLP V4: Inner pan assembly for one lamp	To discontinue after SP support end date
1412.10.010	TLP V3: Inner pan assembly for two lamps	Already discontinued
1412.10.011	TLP v4: Inner pan assembly for two lamps	To discontinue after SP support end date

SP code	SP name	Availability
4072.76.560	White Labyrinth gasket, white, pack of 10	To remain available until F-range discontinuation
4072.76.570	White Labyrinth gasket, white, pack of 100	To remain available until F-range discontinuation
SP.010557	Film disc cut-out (10 pcs)	To remain available until F-range discontinuation
SP.010699	Lamp: halogen lamp, 40W - 6.6A, female connectors (10 pcs)	To discontinue after SP support end date
SP.010762	Wire clamp (100 pcs)	To discontinue after SP support end date
SP.010809	Prism gasket for two windows TLP (10 pcs)	To discontinue after SP support end date
SP.010810	TLP Filter, dichroic, Green (10 pcs)	To discontinue after SP support end date
SP.010811	TLP Filter, dichroic, Yellow (10 pcs)	To discontinue after SP support end date
SP.010812	Gasket between 8" inner pan / cover, for LTS, LTC and TLP (10 pcs)	To discontinue after SP support end date
SP.010813	Filter gasket for TLP (10 pcs)	To discontinue after SP support end date
SP.010816	Lamp spring for TLP (10 pcs)	To discontinue after SP support end date
SP.010818	Prism gasket for one window TLP (10 pcs)	To discontinue after SP support end date
SP.010823	TLP Filter, dichroic, Red (10 pcs)	To discontinue after SP support end date
SP.010869	Screw: pressure release screw assembly including O-ring (10 pcs)	To remain available until F-range discontinuation
SP.013033	kit FAA PLUG STYLE 6 2,5 ² L=400MM PTFE (5pcs)	To remain available until F-range discontinuation
SP.013036	TLP Prism Kit straight Bidirectional	To discontinue after SP support end date
SP.013037	TLP Prism Kit straight Unidirectional	To discontinue after SP support end date

SP code	SP name	Availability
SP.013038	TLP Prism Kit Straight Stop bar Uni	To discontinue after SP support end date
SP.013039	TLP Prism Kit curved Bi, 1 centr. lamp	To discontinue after SP support end date
SP.013040	TLP Prism Kit curved Bi, 2 lamps	To discontinue after SP support end date
SP.013041	TLP Prism Kit LEFT Uni, 1 side lamp	To discontinue after SP support end date
SP.013042	TLP Prism Kit RIGHT Uni, 1 side Lamp	To discontinue after SP support end date
SP.013068	F-range/TLP Fast-on 2.5mm2, female (100pcs)	To remain available until F-range discontinuation
SP.4071.97.091	Blanking screen for TLP (10 pcs)	To discontinue after SP support end date
SP.7100.10.125	Screw: Torx, M4 x 14, DIN 7985-TX-A2 (100 pcs)	To discontinue after SP support end date
SP.7110.08.360	Screw: Torx, M4 x 10, DIN 7500 CE-TX-A2, Taptite (100 pcs)	To remain available until F-range discontinuation
SP.7284.10.416	Washer: lock washer, M4, Inox, DIN 127B (100 pcs)	To remain available until F-range discontinuation

Last-Time Buy Conditions:

- All purchase orders for last -time buys are non-cancellable and non-returnable.
- For orders for only spare parts, a €150 order minimum is required.
- Leadtime of the spare parts to be confirmed upon order confirmation.
- During the final stage of a Spare Part Supply phase ADB SAFEGATE can no longer guarantee full support for the affected products. Spare parts are provided depending on the available inventory; repair and replacement services also depend on component availability.